MONTHLY EDITION NUMBER 32

ISSUED BY: COMMANDER, THIRTEENTH COAST GUARD DISTRICTO(n) 915 Second Avenue, Seattle, Washington 98174-1067

Telephone (206) 220-7270 FAX # (206) 220-7285

BROADCAST NOTICES TO MARINERS INMs)

This Local Notice to Mariners (LNM) includes information concerning waterways in the Thirteenth Coast Guard District promulgated by the following broadcasts:

BNM 0764-97 to 078#-97

LIGHT LIST REFERENCE: COMDTINST M16502.6, Light List Volume VI, 1996 Edition

Electronic Bulletin Board Service: (703) 313-5910 300 to 28.8 bps, 8 data bits, no parity, 1 stop bit

NIS watchstander, 24 hours a day at (703) 313-5900

INTERNET ADDRESS

HTTP://www.navcen.uscg.mil

or

FTP://ftp.navcen.uscg.mil

I. SPECIAL NOTICE

WASHINGTON - GRAYS HARBOR - SCRIPPS INSTITUTION OF OCEANOGRAPHY AND U.S. ARMY CORPS OF ENGINEERS - Deployment of Waverider research buoy -

A deep water wave measurement Waverider) buoy has been deployed in approximate position 46 degrees 51.44 minutes north, 124 degrees 14.66 minutes west, in 22 fathoms. This buoy is a 3 foot diameter yellow sphere with an attached telemetry whip antenna and a night time yellow flashing light. The light timing sequence is a series of 5 flashes at 1 second intervals with a period of 20 seconds between each series, and a visual range of 1 kilometer. The buoy is marked "WAVE BUOY" with the phone number 619-534-3032.

PACIFIC OCEAN - OREGON - NATIONAL OCEANIC AND ATMOSPHERIC ADMINISTRATION (NOAA) - Temporary Buoy Deployment -

A data collection buoy will be established in approximate position 45 degrees 57 minutes north, 130 degrees 0 minutes west. This buoy will be orange and white, showing a Flashing White (group 3) 3 second, Fl W (3) 3s. The buoy will be on station for approximately one year.

Chart 501

CANADA - REGULATORY REQUIREMENTS FOR FOREIGN COMMERCIAL FISHING VESSEL ENTERING CANADIAN WATERS -

The Coastal Fisheries Protection regulations were amended 16 July 1996 to introduce new requirements for foreign commercial fishing vessels. Department of Fisheries and Oceans is reminding affected parties that these requirements are still in effect.

Please be advised that masters of foreign commercial fishing vessels must, as soon as reasonably possible, after entering Canadian waters:

- 1. Notify the Department of Fisheries and Oceans of the name, flag, state, location, route and destination of the vessel and of the circumstances under which it entered Canadian fisheries waters.
- 2. Ensure that all fishing gear on board the vessel is stowed below deck or otherwise removed from the place where it is normally used for fishing and placed where it is not readily available for fishing, and

3. Where requested by a Protection Officer, proceed to a specified location so that a west inspection can be conducted.

These requirements do not apply to foreign fishing vessels operating under a Canadian fishing license. In addition, they do not apply to United States sport fishing vessels conducting normal sport fishing activities.

Affected vessel masters can notify Department of Fisheries and Oceans on the following Marine Communications and Traffic Service channels 71, 11, or 22A. At that time, fishery officials will advise if a vessel inspection is required and provide information on gear stowage.

The primary reason for the requirements is conservation. Failure to comply with requirements is viewed as a serious offense. The Coastal Fisheries Protection Act specifies a maximum penalty of \$100,000.

WASHINGTON - PUGET SOUND - EAGLE HARBOR Remediation Project -

Remediation work will take place east and west of the two piers located at the Washington State Ferries Eagle Harbor Repair Facility. Work will commence 16 June 1997 and continue through September 1997. Five marker buoys with "KEEP OUT" signs on them will be positioned around the work area. There will be derrick barges and material barges on the project site for the duration of the project. Barge mooring lights will be displayed on corners of the barges at night time. VHF-FM Channel 16 will be monitored during the working hours of 0700 to 1900, Monday through Friday, the call sign is "WPR5640".

Chart 18445, 18449 and 18474

OREGON - WILLAMETTE RIVER - OSWEGO ROCK DAYBEACON 12 - Temporary Marker -

On 29 July 1997 Oswego RocDaybeacon 12 was reported missing. A red float with red reflective tape has been placed in the approximate location of the missinglaybeacon. Mariners are urged not to transit too close to the red marker, as part of the structure may remain below the surface.

Chart 18526

 $WASHINGTON-PUGET\ SOUND-HEIN\ BANK-HARO\ STRAIT-ROSARIO\ STRAIT Hydrographic\ Survey$

The Pacific Hydrographic Party will be conductingly drographic survey operations in Puget Sound from the Strait of Juan De Fuca near Hein Bank into Haro Strait up to False Bay and into Rosario Strait up to the north end of Lummi Island. Survey operations are scheduled to begin the week of 16 June 1997 and last for approximately two years. Mariners may contact the survey vessel on VHF-FM Channels 16 or 13 and are asked to keep clear during survey operations. Any person with knowledge of chart deficiencies which should be investigated during this survey may contact the Chief of Party at:

Pacific Hydrographic Party National Ocean Service, NOAA P.O. Box 189 Anacortes, WA 98221

Voice: 360-293-5171 Fax: 360-293-8456

Charts 18400, 18421, 18423, 18424, 18427, 18429, 18430, 18433, 18434, 18440, 18441, 18465, and 18471.

REPORT DEFECTS IN AIDS TO NAVIGATION TO THE NEAREST COAST GUARD UNIT

I. SPECIAL NOTICE (continued)

WASHINGTON - SNAKE RIVER - JUVENILE CHINOOK SALMON MONITORING - Deployment of Four Small Barges -

Two barges will be deployed upstream of Little Goose Lock and Dam and two will be deployed upstream of Lower Monumental Lock and Dam. These sites are located inside the upstream boundary of the boat restricted zone (BRZ) above each of the two dams. The following are the locations of each barge:

Lower Monumental Dam Location 1 46²33'58.5"N 118²32'02.4"W

Location 2

46²33'51.7"N 118²31'55.6"W

Little Goose Dam Location 1 46²35'07.0"N 118²01'09.4"W

Location 2

46²01'18.0"N 118²01'12.0"W

While anchored at the above locations the small barges will study theory ements of juvenile fall Chinook salmon. Each barge will be lighted with two flashing yellow lights showing Flashing Yellow 4 second (Fl Y 4s).

Chart 18545

CANADA - STRAIT OF JUAN DE FUCA - Research Equipment Deployment -

The University of Victoria plans to deploy five closely spaced moorings holding research equipment in the central Strait of Juan deFuca for a period of 5 weeks between 13 July and 15 August 1997. The moorings have no surface markers. Three of the mooring will extend from the sea-floor within 15-20 meters of the sea surface and pose a potential hazard to any net fishing activity. The remaining two moorings extend only 2 meters above the sea-floor and should not represent a danger to navigation or fishing activity except, for bottom trolling. The following are approximate position of the moorings:

Mooring 1 Mooring 2
48²23'21"N 124²05'57"W 48²23'39"N 124²05'45"W
2 Meters above sea-floor 2 Meters above sea-floor
Mooring 3 Mooring 4
48²23'09"N 124²00'09"W 48²23'54"N 124²06'18"W
105 Meters above sea-floor 80 Meters above sea-floor

Mooring 5

48²23'24"N 124²05'00"W 80 Meters above sea-floor

CANADA - STRAIT OF JUAN DE FUCA - Research Surveys -

The University of Victoria will be conducting surveys (during daylight hours only) of temperature, salinity and optical transmissivity from the R/VStrickland on 15 an 16 July and between 11 and 15 August 1997. The expected station positions are as follows:

48²17.8'N 124²11.6'W 48²15.5'N 124²11.1'W 48²16.6'N 124²10.3'W 48²17.8'N 124²09.6'W 48²19.4'N 124²08.6'W 48²21.1'N 124²07.6'W

48²22.5'N 124²06.8'W 48²22.9'N 124²06.3'W 48²24.0'N 124²05.5'W 48²25.2'N 124²04.8'W

There may also be a survey from the R/V Vector during the weeks of 04 and 11 August 1997, with stations in the following positions:

48²14.0'N 123²30.0'W 48²14.2'N 123²40.0'W 48²15.9'N 123²50.0'W 48²17.6'N 123²00.3'W 48²20.4'N 124²10.0'W 48²23.1'N 124²20.0'W 48²27.7'N 124²30.0'W 48²28.7'N 124²40.0'W

II. DISCREPANCIES - DISCREPANCIES CORRECTED

THE FOLLOWING AIDS TO NAVIGATION ARE NOT WATCHING AS ADVERTISED IN THE LIGHT LIST VOLUME VI, THIRTEENTH DISTRICT SECTION:

• Underlined text denotes new discrepancy since last LNM.

FEDERAL AIDS

LL # 09275 97	Aid Na 23/97	me Status Chart BNM LNM UMPQUA RIVER LB 6A	OFF STAT	ΓΙΟΝ	18584	0604-
09285		WINCHESTER BAY HBR ENTRANCE	DBN 1	MISSING		
18584	1322-9	6 49/96				
09315		UMPQUA RIVER LIGHT 15	MISSING		18584	1329-
96	49/96					
11165		WILLOW DIKE LIGHT 26	EXTINGU	ISHED	18524	0769-
97	32/97					
15040		OSWEGO ROCK DAYBEACON 12	M	ISSING		18528
0683-97	7	27/97				
15190		WILLAPA BAY ENTRANCE BUOY 8	M	ISSING		18504
0036-97	7	02/97				
15585		POINT CHEHALIS RANGE FRONT LIC	SHT IM	IPROPER CHARAC	TERISTIC	C
18502	0430-9	7 15/97				
15615		GRAYS HARBOR SOUTH REACH A R	R LIGHT	MISSING TOF	DAYBO	ARD
	18502	0416-97 15/97				
15965		JOHNS RIVER DAYBEACON 3	D/	AYBOARDS MISSIN	1G	
18502	0536-9	7 20/97				
18850		LACONNER RANGE FRONT LIGHT 18	3 MI	ISSING		18427
0198-95	5	08/95				
19005		CAP SANTE DAYBEACON 3	DESTROY	/ED	18427	0537-
97	20/97					

PRIVATE AIDS

LL# Aid Name Status Chart BNM LNM NONE

NOTE: Mariners are cautioned that portions of missing structures may remain.

THE FOLLOWING AIDS TO NAVIGATION DISCREPANCIES HAVE BEEN CORRECTED SINCE THE LAST LOCAL NOTICE TO MARINERS:

FEDERAL AIDS

Aid Name Status Chart BNM LNM

16001 WESTHAVEN LIGHT 7 WATCHING PROPERLY 18502 0784-97

18/97

16335 NEW DUNGENESS LIGHT

WATCHING PROPERLY

18471 0768-

97 31/97

II. DISCREPANCIES - DISCREPANCIES CORRECTED (continued)

PRIVATE AIDS

LL# Status Chart BNM LNM Aid Name

POINT HUDSON MARINA LIGHT 17535 TEMP DISCONTINUED

18441 0450-97 16/97

III. TEMPORARY CHANGES - TEMPORARY CHANGES CORRECTED

LEGEND: TRUB = Temporary Unlighted Buoy

TRLB = Temporary Lighted Buoy

TRLT = Temporary Light

THE FOLLOWING AIDS TO NAVIGATION HAVE BEEN TEMPORARILY CHANGED:

LL # 09285 96	Aid Nai 49/96	me Status WINCHESTER	•	BNM BR ENT	LNM RANCE	DBN 1		TRUB		18584	1322-
09315	40/00	UMPQUA RIVE	R LIGH	T 15		TRLB		18584	1329-9	6	49/96
09520		SIUSLAW RIVE	R CHAN	NNEL D	BN 14		TRUB			18583	0238-
96	08/96										
09560		SIUSLAW RIVE	R CHAN	NNEL D	AYBEA	CON 26		TRUB			18583
0351-96	3	09/96									
09856		GARIBALDI CH	IANNEL	LT 14		TRUB			18558	0953-9	5
32/95											
11365		GOVERNMEN ^T	ΓISLANI	D SOU	TH CH D	BN 19		TRUB			18531
0674-96	3	19/96									
16790		SHILSHOLE BA	Y BREA	AKWAT	ER LIGI	HT 3	SOUNI	O SIGNA	AL DISC	ONTINU	IED
18446	1315-9	6 48/96									
19005		CAP SANTE DA	AYBEAC	CON 3		TRUB			18427	0550-9	7
20/97											

THE FOLLOWING TEMPORARY AIDS TO NAVIGATION HAVE EITHER BEEN RESTORED TO NORMAL OPERATION OR DISCONTINUED:

LL# Aid Name Status Chart BNM LNM

NONE

IV. CHART CORRECTIONS

Corrective action affecting charts is contained in this section. Chart corrections are listed numerically by chart number. The correction listed pertains to that chart only. It is up to the mariner to decide what charts are to be corrected. The following example explains the individual elements of a typical correction.

Chart Chart **Edition Last Local Notice** Source of

Current Local

number edition date to Mariners	Datum Correction							
Notice to Mariners	I I							
18555 1 st Ed. 1/16/56 Last LNM 1/69 03/95	NAD 83 (GS-95)							
ID - FRANKLIN LAKE - LEE HARBOR - PARKER (CGD13)	R WATERWAY -							
Add Parker Channel Light "2", FI R 4sec 45FT 116 ² 20'30"W	Γ 8M 48²24'57"N							
Corrective Object of corrective Position								
action The letter (M) immediately following the chart number indicates that the correction should be applied to the metric side of the chart only. (Temp) indicates that the chart correction action is temporary in nature. Courses and bearings are given in degrees clockwise from 000 true. Bearings of light sectors are toward the light from seaward. The nominal range of lights is expressed in nautical miles.								
18440 23 rd ed., 08/05/95 LAST LNM 29/97 NAD 83 (CGD13)32/97	WA - PUGET SOUND							
Relocate PITT PASSAGE ROCKS DAYBE (47213'5.3"N, 122242'58.5"W) to	EACON from 47 ² 13'09.4"N							
122 ² 43'00.7"W								
18441 38 th ed., 01/25/97 LAST LNM 18/97 NAD 83 (NOS SILVER SPRING)32/97 ADMIRALTY INLET - PORT GAMBLE -	WA - PUGET SOUND- NORTHERN PART -							
Change Puget Sound Traffic Lane Separa open buoy symbol, (Chart No. 1, symbol 4725752.3"N 12223446.5"W								
18445 26 th ed., 06/03/95 LAST LNM 29/97 NAD 83 (CGD13)32/97	WA - PUGET SOUND -							
POSSESSION SOUND TO OLYMPIA INCLUDING HOOD CANAL								
Relocate PITT PASSAGE ROCKS DAYBE (47213'5.3"N, 122242'58.5"W) to	EACON from 47 ² 13'09.4"N							

122²43'00.7"W

18448 28th ed., 06/29/96 LAST LNM 29/97 NAD 83 WA - PUGET SOUND - SEATTLE TO

OLYMPIA (CGD13)32/97

> PITT PASSAGE ROCKS DAYBEACON from Relocate

(47213'5.3"N, 122242'58.5"W) to 47213'09.4"N

122243'00.7"W

18531 18th ed., 02/19/94 LAST LNM 29/97 NAD 83 OR & WA - COLUMBIA RIVER -(NOS CL-873/97) 32/97

VANCOUVER TO THE DALLES

2 ft sounding to 20 ft Change 45²40'50.0"N 121²16'31.0"W

18545 13th ed., 03/03/90 LAST LNM 26/97 NAD 83 WA - SNAKE RIVER - LAKE SACAJAWEA

(CGD13)32/97

Change Snake River Mile 6 Range Front Light, to

KRW 46²14'25.3"N

118257'51.5"W

Snake River Mile 6 Range Rear Light, to

KRW 46²14'33.5"N

118257'25.3"W

18587 66th ed., 08/19/95 LAST LNM 29/97 NAD 83 (CGD13)32/97

(TEMP) OR - COOS BAY

Add

Coos Bay Mooring Buoy, White with Blue Stripe 43²25'18.0"N

124²15'37.0"W

V. ADVANCE NOTICE OF CHANGES IN AIDS TO NAVIGATION

NONE

VI. PROPOSED CHANGES IN AIDS TO NAVIGATION

Comments may be sent to the address on page one of this Local Notice to Mariners.

Comments are requested on or before 01 September 1997Attn: LTJG Steve Wheeler.

WASHINGTON - PUGET SOUND - SEATTLE TO OLYMPIA - Aid to Navigation Change -

The Coast Guard proposes to discontinue Eagle Island Sector Light (LLNR 17270) and establishalch Passage Light 9 (LLNR 17270) approximately 30 yards north of the sector light's position, to better mark the approach and transit through this waterway.

VI. PROPOSED CHANGES IN AIDS TO NAVIGATION (continued)

Comments may be sent to the address on page one of this Local Notice to Mariners.

Comments are requested on or before 01 September 1997Attn: LTJG Steve Wheeler.

WASHINGTON - ADMIRALTY INLET AND PUGET SOUND TO SEATTLE - ADMIRALTY INLET - Light Operation Change

The Coast Guard proposes to change the operation of Marrowstone Point Light (LLNR 16500) from lighted throughout 24 hours to night-time operation only.

VII. GENERAL

DREDGING IN PROGRESS OR PLANNED WITHIN THE f^{h} 3COAST GUARD DISTRICT. MARINERS ARE ADVISED TO NAVIGATE WITH CAUTION AND REDUCE THEIR WAKE WHEN TRANSITING THESE AREAS:

LocationAreaStartCompleteChartGrays HarborCow Point03/09/9708/14/9718502

Willapa Harbor Bar Middle Channel 07/25/97 08/15/97 18504

FISHERIES/BIOLOGICAL SAMPLING, PIER CONSTRUCTION, HYDROGRAPHIC SURVEYS, ETC., CURRENTLY IN PROGRESS WITHIN THE 1th COAST GUARD DISTRICT. ALL MARINERS ARE ADVISED TO NAVIGATE WITH CAUTION WHEN TRANSITING THESE AREAS:

Location Area Start Complete Type of Work

Lk. Wash. Ship Canal Fremont Bridge 05/06/97 08/30/97 Scheluled Maintenance

Lake Washington Evergreen Floating Bridge 06/01/97 09/17/97

Maintenance work

Tacoma Blair Waterway 01/28/97 To Be Announced 11th St. Bridge

Demolition

Snohomish River State Route 529 Bridges 05/06/97 To Be Announced

Replacement of old lift cables

WASHINGTON - PUGET SOUND - Marine Events - Puget Sound Area -

									-	
AREA/LOCATION	DATE 1	TIME	EVENT		SPC	NSOR		PHONE	: #	
Padilla Bay 08/13/9	7 1	1830-22	200	Sail Bo	at Race	Anacor	tes YC	293-573	34	
Commencement Bay										07
Meadow Pt 08/13/9										789-
1919										
Port Ludlow/Snake Roc	k (08/14/9	7	1400-20	000	Sail Bo	at Race	Port Lu	dlow YC	437-
0814										
Sinclair Inlet Bremerton	Port Orch	hard	08/14/9	7	1800-2	100	Sail Bo	at Race	Sinclair	Inlet
YC 871-2940										
West Point/Point Wells	08/14/97	•	1600-2	100	Sail Bo	at Race	Corinth	ian YC c	of Seattle	9
789-1919										
Shilshole/Blakely Rock	08/17/97	•	1030-18	300	Sail Bo	at Race	Seattle	Singles	YC	914-
2682								J		
Padilla Bay 08/20/9	7 1	1830-21	130	Sail Bo	at Race	Anacor	tes YC	293-573	34	
Commencement Bay										07
Meadow Pt 08/20/9	7 1	1800-21	100	Sail Bo	at Race	Corinth	ian YC d	of Seattle	9	789-
1919										
Port Ludlow/Snake Roc	k (08/21/9	7	1400-20	000	Sail Bo	at Race	Port Lu	dlow YC	437-
0814										
Sinclair Inlet Bremerton	/Port Orch	hard	08/21/9	7	1800-2	100	Sail Bo	at Race	Sinclair	Inlet
YC 871-2940										
Clockwise around Vash	on Island		08/23/9	7	0900-18	800	Sail Bo	at Race	Corinth	ian YC
of Tacoma 395-652	21									
Clockwise around Vash	on Island		08/24/9	7	0900-18	800	Sail Bo	at Race	Corinth	ian YC
and West Marine										
Padilla Bay 08/27/9										
Commencement Bay	08/27/97	•	1800-22	200	Sail Bo	at Race	Windse	ekers	838-520	07
Meadow Pt 08/27/9	7 1	1800-21	100	Sail Bo	at Race	Corinth	ian YC d	of Seattle	9	789-
1919										
Sinclair Inlet Bremerton	/Port Orch	hard	08/28/9	7	1800-2	100	Sail Bo	at Race	Sinclair	Inlet
YC 871-2940										
West Point/Point Wells	08/31/97	•	1600-2	100	Sail Bo	at Race	Corinth	ian YC c	of Seattle	9
789-1919										

OREGON - Marine Events - Portland Area -

AREA/LOCATION DATE TIME EVENT SPONSOR PHONE #

NONE

WASHINGTON - GRAYS HARBOR - COW POINT TO CENTER OF CROSSOVER CHANNEL - Dredge Operations -

Dredging operations have commenced from Cow Point to the center of Crossover Channel. These operations will be 24 hours per day, 7 days a week and will continue until 14 August 1997. The vessels involved are the Derrick Barge VIKING, Towboat WOLLOCHET, and the Towboat MARIE M. The operating vessels will monitor VHF-FM Channels 13 and 16. Properdayshapes and lights will be displayed during these operations.

Chart 18502

WASHINGTON - PUGET SOUND - HOOD CANAL - Bridge Information -

The new phone number to contact the Hood Canal Bridge for openings is (360)779-3233. A minimum of one hour advanve notice is required for bridge openings. The Bridge tenders monitor VHF-FM 13 thirty minutes prior to scheduled openings.

WASHINGTON - WILLAPA HARBOR - Dredging Operations -

The Seattle District, Corps of Engineers advises that the hopper dredge YAQUINA will be conducting dredging operations in Willapa Harbor on the Bar Middle Channel during the period 25 Julthru 15 August 1997. Dredging will be done by side casting.

Chart 18504

WASHINGTON - LAKE WASHINGTON - EVERGREEN POINT FLOATING BRIDGE, STATE ROUTE 520 - Bridge Information -

The draw of the 520 Bridge need not open for the passage of vessels from 0600 local on 18 August to 1800 local 17 September 1997. This closure is to accommodate scheduled maintenance.

Chart 18447

WASHINGTON - PUGET SOUND - SNOHOMISH RIVER - Bridge Information -

The dual vertical lift span bridges across the Snohomish River at Everett on State Route 529 are unable to open for the passage of vessels until the old lift cables are replaced. The drawbridges will remain in the closed position until further notice.

Charts 18443 and 18444

VII. GENERAL (continued)

WASHINGTON - PUGET SOUND - LAKE WASHINGTON SHIP CANAL - Bridge Information -

The Fremont Bridge need not provide double-leaf openings for the passage of vessels unless one hour notice is provided Monday through Friday from 0600 local to 2200 local and from 0700 local to 2200 local on Saturday from 06 May to 30 August 1997. The painting of the bridge will occasionally require the placement of containment material beneath the bridge which may reduce vertical clearance by as much as three feet.

Chart 18447

WASHINGTON - TACOMA HARBOR - BLAIR WATERWAY - Bridge information -

The 11th Street Bridge is being demolished. Thedrawspans have been removed. Red pier protection lights will remain operational until the structure is removed. Floating equipment will move out of the channel as needed for the passage of vessels.

Charts 18453 and 18474

WASHINGTON - SNAKE RIVER - Two Mooring Buoys Deployed -

Two mooring buoys were established upstream of Lower Granite Lock and Dam. One is on the south side of the river approximately 150 yards from the south shore in approximate position 46²39'08.4"N 117²24'29.5"W. The other is approximately 150 yards off the north shore in approximate position 46²39'25.9"N 117²24'24.4"W. These mooring buoys will remain until mid summer.

Chart 18547

OREGON - COOS BAY SOUTH SLOUGH - WATERWAY ANALYSIS - Request for Comments -

The Coast Guard is conducting an analysis of The Coos Bay Soutslough (Light List numbers 9135 to 9775) to evaluate the adequacy of the aids to navigation. Users of this waterway area are invited to comment on the current system. All comments should be received by 01 September 1997 at: Commander, USCG Group North Bend, 2000 Connecticut Avenue, North Bend, OR 97459-2399Attn: BMC Berry (SurfOps). Additionally, if you would like to participate in a survey being conducted on this waterway, fill out the information sheet in enclosure (1) to this Local Notice to Mariners, and mail it to the above address.

Chart 18587

WASHINGTON - PUGET SOUND - ADMIRALTY INLET - WATERWAY ANALYSIS - Request for Comments -

The Coast Guard is conducting an analysis of Admiralty Inlet bounded by Point Wilson LB 6 (Light List numbers 16470) and Puget Sound Traffic Lane Separation LB SE) to evaluate the adequacy of the aids to navigation. Users of this waterway area are invited to comment on the current system. All comments should be received by 01 September 1997 at: Commanding Officer, USCGC MARIPOSA, 1519 Alaskan Way South, Seattle, WA, 98134-1192, Attn: ENS Hoory. Additionally, if you would like to participate in a survey being conducted on this waterway, fill out the information sheet in enclosure (2) to this Local Notice to Mariners, and mail it to the above address.

VIII. CORRECTIONS TO LIGHT LIST, VOLUME VI; PACIFIC COAST AND PACIFIC ISLANDS 1997:

An asterisk *, indicates the column in which a correction has been made or new information added.

 $\phi\phi\phi\phi\phi\phi\phi\phi\phi\phi$

(1) No.	(2) (3) (4) Name and location Remarks Umpqua River	(5) (6) Position	(7) (Characte	8) eristic	Ht	Rng	Structure
9300	- LIGHT 12 32/97	FIR 4s	22	4	TR on	platform	

Snake River

13160 MILE 6 RANGE FRONT 46 14.4 Q W 26 KRW on tower. Visible all around; higher LIGHT118 57.9 intensity on rangeline.

• 32/97

13165 MILE 6 RANGE REAR LIGHT	Iso W 6s	45	KRW on tower. Visible			
4 ² each side of						
679 yards, 0642 from		rangeline.				
front light.						

Carr Inlet

32/97

17298 Pitt Passage Rocks 47 13.2 NW on pile worded

Daybeacon 122 43.0

• 32/97

DANGER SHOAL.

Fort Peck Lake

20275	- LIGHT E	Fl W 6s	25	6	NB on platform.
•	32/97				
20285	- LIGHT G	FI W 2.5s	25	6	NB on platform.

IX. ADDITIONAL ENCLOSURES:

- 1. Waterway Analysis for Coos Bay Sout Slough Chart 18587, request for comment.
- 2. Waterway Analysis for Admiralty Inlet Chart 18441, request for comment.

If you have any questions, comments, or need additional information concerning this or otheNMs or the LNM Mailing List (e.g. additions, deletions, corrections) contact the address or phone number on the front page.

W. D. WIEDENHOEFT

Commander, U.S. Coast Guard
Chief, Aids to Navigation & Waterways Management Branch
Thirteenth Coast Guard District
By direction of the District Commander 2
COMMANDER, THIRTEENTH COAST GUARD DISTRICT
LOCAL
NOTICE TO MARINERS NO. 32

05 August 1997 PAGE # OF 5 NOTICE NO. 32